

Inactive Disposal Site Monitoring Results for 10/22/84

	<u>North Site</u>		<u>South Site</u>	
	<u>Well 2</u>	<u>Well 4</u>	<u>Well 3</u>	<u>Well 4</u>
TOC, ppm	5	3	3	3
pH	6.1	6.1	6.4	6.4
Chloride, ppm	4.9	4.6	4.4	70
Metals, ppm				
As*	<0.05	<0.05	<0.05	<0.05
Cd*	<0.01	<0.01	<0.01	<0.01
Cr*	<0.05	<0.05	<0.05	<0.05
Cu	<0.05	<0.05	<0.05	<0.05
Hg*	<0.002	<0.002	<0.002	<0.002
Pb*	<0.05	<0.05	<0.05	<0.05
Ni	<0.1	<0.1	<0.1	<0.1
Ag*	<0.05	<0.05	<0.05	<0.05
Zn	<0.05	<0.05	<0.05	<0.05
Organics, ppb**				
Toluene	<10	<10		
Acrylonitrile	<100	<100		
PCB-1242	<1.0	<1.0		
PCB-1254	<1.0	<1.0		
PCB-1221	<1.0	<1.0		
PCB-1232	<1.0	<1.0		
PCB-1248	<1.0	<1.0		
PCB-1260	<1.0	<1.0		
PCB-1016	<1.0	<1.0		

*Drinking water standards have been established for these metals.

**See attached Kemron report for complete volatile organic and pesticide priority pollutant analyses.

V.02B.35

These are the results of groundwater monitoring conducted at the North and South inactive disposal sites on 10/22/84. Wells #2 and #4 at the North site and wells #3 and #4 at the South site were the only wells to yield samples; the other wells (north site wells #1, #2A, and #6 and south site well #2) were dry.